



Project 1005 Craven St.
Subject: Job Progress Photographs
Photo Date: 10.02.12.



From Rear, Porch Roof in place, Windows Installed
Waiting on door delivery



Windows & Hydrostatic Vent, Sample Siding & Trim
Note Column strapping to face of porch beam

Non beveled siding protrudes beyond trim



Beveled Siding Puts lap behind 5/4" trim



View out of Window at sink in Apartment looking to Charles Street



Looking to future "Bridge" & Pergola
Porch floor protected from weather by house wrap



Second Floor with bathroom windows & New Roof over roof over Porch & Laundry



Looking to Garage from Screen Porch
Note beam above



Side facing Rhett House (Garage/Apt in background)



Looking out from Kitchen Sink to Rhett House Yard



New Window in Lower Level

Smaller Scale trim & drip cap than that on upper portion of House




Owner's Bathroom Window Wall



To owners Bath from Dressing - Vanity sinks to be centered below windows



Doors arrive in between rain showers



Instructions for trim below Porch Floor & Strapping @ new-existing joint



September 7 less than a month ago...
Good Job Lance