



Project 1005 Craven St.
Subject: Job Progress Photographs
Photo Date: 9.11.12



New Second Floor-Roof off rear in prep for reframing



New Second Floor & Reframed roof over Side Porch



Side Porch



View from Banquette to Dining Room
Wall removed to Repair Sliding Door Mechanism




Repositioned Window in Stairwell
(Reused from Guest Bathroom)



Looking to Shower from Spa/Tub Area
(Bottom of Center Windows 80" off floor)



Looking Out Bathroom Window towards Garage
Roof of Laundry in foreground



Looking to Garage @ Bridge Location



Floor Ceiling Framing in Garage
Large 24" deep center beam flush framed with TGI Floor joists



Front View of Garage
Framing for Hydrostatic Vents, All wood PT to Plates



View out New Stair Window